


ATTACHMENT C
PICTURES OF HISTORICAL RESOURCES AFFECTED BY ALTERNATIVES

The following photographs were taken to illustrate the condition of historical resources affected by alternatives in the study area. The dates of each photograph are included in the caption if known. The aerial map preceding the photographs provides a key that indicates the locations where each photo was taken.



-  Fairbourn Historic District
-  Fairbourn Developed Areas

-  Photo Position
Arrow points in direction photo was taken

**11400 South Study Area
Detail Photo Locations**



Photo A (August 2005) – 191 West 12600 South



Photo B – 736 West 12300 South



Photo C – 2779 West 12600 South



Photo D – 11407 South 1300 West



Photo E (August 2005) – from north side of I-15 overpass at 11400 South looking West



Photo F (August 2005) – from north side of I-15 overpass at 11400 South looking northwest



Photo G (August 2005) – approx. 250 West 11400 South



Photo H (August 2005) – 455 West 11400 South



Photo I (August 2005) – looking north from east of Jordan Gateway and 11400 South



Photo J (August 2005) – looking northwest from east of Jordan Gateway and 11400 South



Photo K (August 2005) – looking north-northwest from east of Jordan Gateway and 11400 South



Photo L (August 2005) – looking west-northwest from east of Jordan Gateway and 11400 South



Photo M (August 2005) – approx. 200 West 11400 South



Photo N (August 2005) – 455 West 11400 South



Photo O (August 2005) – approx. 260 West 11400 South



Photo P (August 2005) – approx. 170 West 11400 South



Photo Q (December 2003) – Bridge over Jordan and Salt Lake Canal, approx. 200 West 11400 South